

## INFORMATION REPORT INFORMATION REPORT

## CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

C-O-N-F-I-D-E-N-T-I-A-L

25X1

COUNTRY China

REPORT

25X1

SUBJECT Port Information, Taku Bar

DATE DISTR. 1 October 1955

NO. OF PAGES 2

25X1

DATE OF INFO.

REQUIREMENT

PLACE ACQUIRED

REFERENCES

25X1

DATE ACQUIRED

This is UNEVALUATED Information

SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE.

25X1

Dredging Activity and Nautical Data

1. The maintenance at Taku Bar [ ] was limited exclusively to keeping the channel at its correct depth. There was a large hopper-barge dredger working in the channel. 25X1
2. The accuracy of the channel depth of 24 feet as indicated on the Admiralty Chart ~~may have been in error.~~ [ ] The depth of the channel was estimated at a maximum of 22 feet at high tide. 25X1

Docks and Piers

3. [ ] The pier, probably built by the Japanese during the last war, was not kept up nor improved. The pier walls were in a neglected condition. 25X1
4. The west side of the new port was bordered by newly dredged up earth. No new pier walls had been built to partition off the water.
5. The breakwaters had partly fallen apart and the electric standards (lichtmasts) placed on them were all askew. In general the harbor gave an unkept appearance.
6. The harbor had a coal storage area with one coal hoist and a small supply of coal.

25X1

25 YEAR RE-REVIEW

C-O-N-F-I-D-E-N-T-I-A-L

25X1

STATE	X	ARMY	X	NAVY	X	AIR	X	FBI		AEC									
-------	---	------	---	------	---	-----	---	-----	--	-----	--	--	--	--	--	--	--	--	--

(Note: Washington distribution indicated by "X"; Field distribution by "#".)

INFORMATION REPORT INFORMATION REPORT

25X1

**Page Denied**